


Fガラス													タイヤ状態 1～10、×、欠、で記載																	
要交換	良好	飛石有											<table border="1"> <tr> <td colspan="2">×</td> <td colspan="2">×</td> </tr> <tr> <td colspan="2">×</td> <td colspan="2">×</td> </tr> <tr> <td>5</td><td>5</td><td>5</td><td>5</td> <td>5</td><td>5</td><td>5</td><td>5</td> </tr> <tr> <td>5</td><td>5</td><td>5</td><td>5</td> <td>5</td><td>5</td><td>5</td><td>5</td> </tr> </table>				×		×		×		×		5	5	5	5	5	5
×		×																												
×		×																												
5	5	5	5	5	5	5	5																							
5	5	5	5	5	5	5	5																							
記録簿			有	無																										
取説			有	無																										
メンテノート			有	無																										
PMマフラ			有	無																										
証明書			有	無																										
燃料タンク																														
									ラジアル																					
									F																					
									サイズ																					
									R																					
									235/75R17.5																					